

Part 573 Safety Recall Report

24V-772

Manufacturer Name : BMW of North America, LLC

Submission Date : OCT 22, 2024

NHTSA Recall No. : 24V-772

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : BMW of North America, LLC

Address : P.O. Box 1227

Westwood NJ 07675-1227

Company phone : 18005257417

Population :

Number of potentially involved : 7

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2025-2025 BMW X3 (X3 xDrive30i, X3 M50i)

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Approximately 7 vehicles have been manufactured with a front passenger air bag that may have been damaged during transport/handling between the Tier 2 and Tier 1 suppliers.

Basis for recall population determination: Vehicle assembly information and supplier production records were used to determine the specific dates of potentially affected vehicles.

Recall component difference to non-recall component: The front passenger air bag may have been damaged during transport/handling between the Tier 2 and Tier 1 suppliers.

Production Dates : JUL 16, 2024 - AUG 19, 2024

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : This safety recall involves the front passenger air bag. During transport/handling between the Tier 2 and Tier 1 suppliers, the air bag fabric may have been damaged.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In a crash in which deployment of the front passenger air bag is warranted, the air bag may not inflate appropriately. This could result in insufficient

restraint capability to the front passenger, which could increase the risk of injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Front Passenger Air Bag

Component Description : Front Passenger Air Bag

Component Part Number : 5A1E2D9

Supplier Identification :

Component Manufacturer

Name : Draexlmaier

Address : 1751 E. Main St.
Duncan South Carolina 29334

Country : United States

Chronology :

Please refer to BMW's September 25, 2024 Part 579 report assigned Foreign Recall ID 24F-220 by NHTSA.

Although initial information indicated that potentially affected vehicles for the US market were all contained, preliminary reviews suggested that a small number of potentially affected vehicles may have been released from the vehicle assembly plant.

In October, further reviews and analyses were conducted to determine which, if any, vehicles may have been potentially affected.

Vehicle assembly information and supplier production records were used to determine the specific dates of potentially affected vehicles.

As a result, BMW will be conducting a voluntary safety recall for these specific vehicles.

Description of Remedy :

Description of Remedy Program : The front passenger air bag will be replaced.

Owner vehicles are not affected and, therefore, mailing of owner notification letters via Part 577 is not necessary.

How Remedy Component Differs from Recalled Component : Recalled Component: front passenger air bag – p/n: 5A1E2D9

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dealer notification is planned to begin and end on October 17, 2024.

Planned Dealer Notification Date : OCT 17, 2024 - OCT 17, 2024

Planned Owner Notification Date : NR - NR

* NR - Not Reported