

# Part 573 Safety Recall Report

# 24V-773

**Manufacturer Name :** Mack Trucks, Inc.**Submission Date :** OCT 21, 2024**NHTSA Recall No. :** 24V-773**Manufacturer Recall No. :** SC0471**Manufacturer Information :**

Manufacturer Name : Mack Trucks, Inc.

Address : 2100 Mack Boulevard

PO Box M Allentown PA 18105-5000

Company phone : 610-709-2131

**Population :**

Number of potentially involved : 49

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2025 Mack GR (Granite) GU (Granite)

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

**Descriptive Information :** The recall population is defined by specific vehicles equipped with non-DOT tested tires sold for use in the US market. Trucks built between 2017-11-01 to 2024-06-24, Mack MY 2018-2025 Granite (GR) 49 units.

Production Dates : NOV 01, 2017 - JUN 24, 2024

VIN Range 1 : Begin : 1M2AX04C0JM040847 End : 1M2GR3GY9SM046631  Not sequential**Description of Defect :**

**Description of the Defect :** Certain vehicle may have been built with non-DOT tested tires, as required by FMVSS 119. Tires that are not confirmed with appropriate DOT standard testing may have failure a which could result in an accident.

FMVSS 1 : 119 - New pneumatic tires- other than passenger cars

FMVSS 2 : NR

**Description of the Safety Risk :** Tires that have not had the appropriate DOT standard testing may have a failure which could result in an accident which could result in injury.

**Description of the Cause :** Mack sales tool did not restrict non-DOT certified tires from sales orders for trucks intended for use in the United States.

**Identification of Any Warning that can Occur :** There are no warnings associated with this issue.

**Involved Components :**

Component Name 1 : Tire

Component Description : BGSTL317

Component Part Number : 3179559

## Supplier Identification :

### Component Manufacturer

Name : Mack Trucks

Address : 7825 National Service Rd.  
Greensboro North Carolina 27409-9667

Country : United States

## Chronology :

Sept 6, 2024: Product engineering is notified by Bridgestone that certain vehicles may have been sold into the US market with non-DOT tested tires.

Sept 13, 2024: Concerned tire is blocked in sales tool for future orders and an investigation is opened.

Oct 9, 2024: Product Compliance Committee meets and reviews finding and recommends that the issue be escalated to the Product Safety Committee as a potential non-compliance.

October 13, 2024: Product Safety Committee meets and determines that a product non-compliance exists and vehicles will be recalled.

October 18, 2024: DIR report filed with NHTSA.

There have been no warranty claims, field reports, accidents or injuries reported with this issue.

## Description of Remedy :

Description of Remedy Program : Vehicles will be recalled and inspected for this tire and non-compliant tires will be replaced.  
Reimbursement for the recall will be covered by Manufacturer's Reimbursement Plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : The remedy component will be a FMVSS 119 DOT compliant tire. Tire, BGSTL317, 3179559.

Identify How/When Recall Condition was Corrected in Production : No vehicles with this tire were in our production facilities and sales order tool will not allow this tire to ordered as of September 13, 2024.

**Recall Schedule :**

Description of Recall Schedule : Dealer notification will begin on or before October 24, 2024 and owner notification will begin on or before December 10, 2024  
Planned Dealer Notification Date : OCT 24, 2024 - OCT 24, 2024  
Planned Owner Notification Date : DEC 10, 2024 - DEC 10, 2024

\* NR - Not Reported