

Part 573 Safety Recall Report**24V-803****Manufacturer Name :** Forest River, Inc.**Submission Date :** OCT 25, 2024**NHTSA Recall No. :** 24V-803**Manufacturer Recall No. :** 400-1857**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 4

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2025-2025 Forest River Inc. Palomino PAT2085BHS Travel Trailers

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The scope was determined to begin at the inception of the models.

2025	PALOMINO	PAT2085BHS	4
Grand Total			4

Production Dates : AUG 13, 2024 - SEP 26, 2024

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The LP Gas manifold block may be installed in the jounce path of the axles' equalizer.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the axles' equalizer contacts the LP gas manifold and cracks it, it may allow LP gas to escape. This may lead to a fire and personal injury.

Description of the Cause : Manufacturing Error.

Identification of Any Warning : An operator may smell LP gas if the manifold is cracked from impact of the that can Occur : axles' equalizer.

Involved Components :

Component Name 1 : LP Gas Manifold

Component Description : LP Gas Manifold

Component Part Number : N/A - INSTALL ISSUE

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On October 18, 2024, Forest River's Office of Corporate Compliance was contacted by the manufacturing plant. The manufacturing plant had indicated that there was a dealer claim against a single vehicle in which the LP gas manifold was located in the jounce pathway of the axle's equalizer. OCC opened a research item the same day. Only one claim was found for this issue.

On October 25, 2024, Forest River's Corporate Recall Committee voted to recall. All vehicles are located at Dealers. A Stop Sale notice is being issued today.

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to relocate the LP Gas Manifold forward by 5 inches.

What is the Forest River Customer Service Phone Number? (269)
432-3246

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Palomino
1047 E M-86
Colon, MI 49040-0802

How Remedy Component Differs from Recalled Component : Affected Component – LP Gas Manifold
The LP Gas Manifold will now be installed away from the jounce path of the axles' equalizer

Identify How/When Recall Condition was Corrected in Production : The week of October 18, 2024, the manufacturing plant began inspecting and moving the LP gas manifold on any affected vehicles in the yard and in production.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : DEC 04, 2024 - DEC 04, 2024

Planned Owner Notification Date : NR - NR

* NR - Not Reported