

# Part 573 Safety Recall Report

# 24V-824

**Manufacturer Name :** Winnebago Industries, Inc.

**Submission Date :** APR 28, 2025

**NHTSA Recall No. :** 24V-824

**Manufacturer Recall No. :** 191



## Manufacturer Information :

**Manufacturer Name :** Winnebago Industries, Inc.

**Address :** PO BOX 152  
605 W. Crystal Lake Rd. Forest City IA  
50436

**Company phone :** 1-641-585-3535

## Population :

**Number of potentially involved :** 5,313

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2020-2024 Winnebago View / Navion

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The recall population was determined by identifying the production dates.

**Production Dates :** MAR 02, 2019 - AUG 22, 2023

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** Certain Lippert (Metallarte) door assemblies were manufactured with inadequate adhesion of the window to the door assembly.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** There is potential for the adhesive used to mount the window in the entrance door to fail over time, which can result in the window becoming loose and/or detaching completely from the door. A window that becomes loose or detached while the vehicle is in transit could become a road hazard to other motorists and increase the risk of a crash.

**Description of the Cause :** Unknown

**Identification of Any Warning that can Occur :** A window that becomes loose in transit will produce a noticeable change in noise level within the vehicle.

## Involved Components :

Component Name 1 : Door Complete - Entrance

Component Description : Entrance Door Assembly

Component Part Number : 329933-01-06A

## Supplier Identification :

### Component Manufacturer

Name : Lippert Components (Metallarte)

Address : 2020 Blakesley Pkwy  
Bristol Indiana 46507

Country : United States

## Chronology :

In late September, Winnebago Product Safety became aware of a concern with the Lippert (Metallarte) door assembly windows with allegations of partial and/or full detachment of the window in transit. An investigation was subsequently opened. During the investigation, Winnebago identified 121 total claims from 2019 to mid-2023. It was also found that Lippert provided repair instructions regarding the process of re-adhering the window to the door assembly.

On October 25, 2024, the Product Safety Committee met and determined that a defect related to motor vehicle safety was present.

Winnebago is aware of 2 unconfirmed detachments in the field and 121 total claims of loose windows. Winnebago is not aware of any injuries or property damage associated with this issue.

## Description of Remedy :

Description of Remedy Program : Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : Remedy is to install clips to secure the window to the door and, if necessary, apply additional adhesive.

Identify How/When Recall Condition was Corrected in Production : Winnebago Motorhomes switched to a new door supplier.

**Recall Schedule :**

Description of Recall Schedule : Recall schedule for notifications will be within the 60 day requirement.

Planned Dealer Notification Date : NOV 22, 2024 - NOV 22, 2024

Planned Owner Notification Date : MAY 30, 2025 - MAY 30, 2025

\* NR - Not Reported