

Part 573 Safety Recall Report

24V-824

Manufacturer Name : Winnebago Industries, Inc.

Submission Date : FEB 21, 2025

NHTSA Recall No. : 24V-824

Manufacturer Recall No. : 191



Manufacturer Information :

Manufacturer Name : Winnebago Industries, Inc.

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 5,313

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2024 Winnebago View / Navion

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying the production dates.

Production Dates : MAR 02, 2019 - AUG 22, 2023

VIN Range 1 : Begin : NR **End :** NR

Not sequential

Description of Defect :

Description of the Defect : Certain Lippert (Metallarte) door assemblies were manufactured with inadequate adhesion of the window to the door assembly.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : There is potential for the adhesive used to mount the window in the entrance door to fail over time, which can result in the window becoming loose and/or detaching completely from the door. A window that becomes loose or detached while the vehicle is in transit could become a road hazard to other motorists and increase the risk of a crash.

Description of the Cause : Unknown

Identification of Any Warning that can Occur : A window that becomes loose in transit will produce a noticeable change in noise level within the vehicle.

Involved Components :

Component Name 1 : Door Complete - Entrance

Component Description : Entrance Door Assembly

Component Part Number : 329933-01-06A

Supplier Identification :

Component Manufacturer

Name : Lippert Components (Metallarte)

Address : 2020 Blakesley Pkwy
Bristol Indiana 46507

Country : United States

Chronology :

In late September, Winnebago Product Safety became aware of a concern with the Lippert (Metallarte) door assembly windows with allegations of partial and/or full detachment of the window in transit. An investigation was subsequently opened. During the investigation, Winnebago identified 121 total claims from 2019 to mid-2023. It was also found that Lippert provided repair instructions regarding the process of re-adhering the window to the door assembly.

On October 25, 2024, the Product Safety Committee met and determined that a defect related to motor vehicle safety was present.

Winnebago is aware of 2 unconfirmed detachments in the field and 121 total claims of loose windows. Winnebago is not aware of any injuries or property damage associated with this issue.

Description of Remedy :

Description of Remedy Program : Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : Remedy is to install clips to secure the window to the door and, if necessary, apply additional adhesive.

Identify How/When Recall Condition was Corrected in Production : Winnebago Motorhomes switched to a new door supplier.

Recall Schedule :

Description of Recall Schedule : Recall schedule for notifications will be within the 60 day requirement.

Planned Dealer Notification Date : NOV 22, 2024 - NOV 22, 2024

Planned Owner Notification Date : MAR 10, 2025 - MAR 10, 2025

* NR - Not Reported