



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

24V913

Manufacturer Name: Forest River, Inc.

Submission Date: Jul 11, 2025

NHTSA Recall No.: 24V913

Manufacturer Recall No.: 68-1875

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 6,963

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2009-2017 Forest River Inc. Georgetown Class A Motorhomes

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Dec 01, 2008 - Dec 22, 2016

Number of potentially involved:

Descriptive Information:

The scope was defined from the inception of purchasing the lamp until the PCN where the lamp ceased to be purchased for manufacturing.
See attached spreadsheet for model and quantity

Defect / Noncompliance Description

Description of the defect or noncompliance:

According to the supplier: "The amber lense does not have the adequate reflective surface area to meet F/CMVSS 108."

FMVSS1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the turn signal lamp does not meet the FMVSS 108 standards, the turn signal may not be conspicuous to a motorist. The condition may lead to a crash.

Part 573 Safety Recall Report

24V913

Description of the cause:

Unknown.

Identification of any warning that can occur:

Unknown.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Kaper II, Inc

Address: 2212 Parrot Way
Kelso WA, 98626

Country: United States

Involved Components

Component Name 1: LIGHT, PARK / TURN, AMBER

Component Description: LIGHT, PARK / TURN, AMBER

Component Part Number: 1S-V-4710A & L50-0036A

Chronology

On November 4, 2024, Forest River's Office of Corporate Compliance was notified that the amber turn signal lamp does not meet FMVSS 108 surface area reflectivity. On November 5, 2024, OCC communicated with the manufacturing plant in order to ascertain if the lamps had been used in any Forest River product. On December 2, 2024, OCC was told by the manufacturing plant that they had identified that the suspect lamp had been used, and which models' year vehicles were affected. As a result, OCC opened a research item. On December 4, 2024, Forest Rivers Corporate Committee voted to recall. On February 5, 2025, Forest River received information from the supplier stating that they are sending a single sample lens to Forest River's manufacturing plant for a physical test. Forest River reached out again to the supplier and the manufacturing plant on March 10, 2025, for an update. At this time, we do not have a schedule of when we will have remedy parts in our hands or available from Kaper II/Future Sales. On March 28, 2025, Forest River received a request from NHTSA to update the remedy status. At this time, we do not have a schedule of when we will have remedy parts in our hands or available from Kaper II/Future Sales. On May 13, 2025, Forest River received a request from NHTSA to update the remedy status. At this time, we do not have a schedule of when we will have remedy parts in our hands or available from Kaper II/Future Sales. On July 11, 2025, Forest River received a request from NHTSA to update the remedy status. At this time, we do not have a schedule of when we will have remedy parts in our hands or available from Kaper II/Future Sales.

Part 573 Safety Recall Report

24V913**Related NHTSA Recall Number:**

Description of Remedy

Remedy Type:**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside**Description of remedy program:**

The remedy for this recall is not available. Once the remedy is available, and amendment will be done.

What is the Forest River Customer Service Phone Number? (574) 206-7600

How remedy component differs from recalled component:

Kaper II, Inc. - (800) 336-2011
2212 Parrot Way
Kelso, WA 98626

Affected Component - LIGHT, PARK / TURN, AMBER
P/N - 1S-V-4710A & L50-0036A
Replacement Component – Unknown

Unknown

Identify how/when recall condition was corrected in production:

For model year 2017, the lamp was not used as a design change to the front cap of the motorhome was used, requiring a different lamp.

Reimbursement Plan

Description of reimbursement program:**Period of reimbursement:****Costs to be reimbursed:****Address for reimbursement claims:**

Recall Schedule

Description of recall schedule:

Part 573 Safety Recall Report**24V913**

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Aug 25, 2025 - Aug 25, 2025

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date:

☐ Phased Recall

Date when VIN will be searchable: