

Part 573 Safety Recall Report

24V-947

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** FEB 13, 2025**NHTSA Recall No. :** 24V-947**Manufacturer Recall No. :** N946**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 11,961

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 100 %

Mahwah NJ 07495

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2022-2023 LAND ROVER RANGE ROVER

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2024MY Land Rover Range Rover vehicles built at the Solihull Vehicle Assembly Plant from March 2, 2022 - December 15, 2023. 11,961 Land Rover Range Rover vehicles in the United States and Federalized Territories. The basis for the recall population of Land Rover Range Rover vehicles was determined by matching the at-risk camera serial numbers to VINs using vehicle build records.

Production Dates : MAR 02, 2022 - DEC 15, 2023

VIN Range 1 : Begin : SALKP9FU2NA003771 End : SALKP9E71PA042673 Not sequential**Description of Defect :**

Description of the Defect : A concern has been identified where, on certain Range Rover vehicles, water could get into the rear-facing tailgate mounted camera. This water ingress can cause a distorted image, or no image at all, to be displayed on the touchscreen.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A blurred image or lack of display of the camera image may result in the driver being unaware of objects or pedestrians increasing the risk of an injury and a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Rear camera

Component Description : Rear camera

Component Part Number : L8B2-19H422-AD

Supplier Identification :

Component Manufacturer

Name : Robert Bosch Ltd

Address : Robert Bosch Ltd

Millburn Hill Road Coventry Foreign States CV4 7HS

Country : United Kingdom

Chronology :

See File "Recall N946 Chronology Revised 13FEB25".

Description of Remedy :

Description of Remedy Program : Vehicles will have the rear camera replaced. There will be no charge to the owners for this repair. Any vehicles under warranty will be covered under JLR's new vehicle warranty program, therefore re-imbusement for pre-notice remedies is not applicable. Customers who have paid for a repair of this defect out of warranty will be reimbursed by JLR's reimbursement plan, subject to the usual terms and conditions.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Notifications to dealers will occur on January 8, 2025. Distribution of owner notification letters will occur on or before February 14, 2025.

Planned Dealer Notification Date : JAN 08, 2025 - JAN 08, 2025

Planned Owner Notification Date : FEB 14, 2025 - FEB 14, 2025

* NR - Not Reported