

SAFETY RECALL N778 – Rear Surround Camera Bezel
- Water Ingress



NAS24.04.002

RECALL

USA/CAN

AFTERSALES BULLETIN

APRIL 3, 2024

TO: All Jaguar Land Rover Authorized Retailers
RE: IMPORTANT INFORMATION FOR IMMEDIATE ACTION

The N778 Recall bulletin was published on TOPIx February 22, 2024, with a Service Instruction and repair for only Range Rover models.

This recall also affects certain Range Rover Sport models, however as detailed in this bulletin, there is currently no repair available for that model.

Retailers should continue to repair affected Range Rover models **but, at this time, must not perform** any N778 recall repairs or submit the campaign warranty claims for Range Rover Sport models. The recall bulletin will be re-issued at a later date with a repair suitable for Range Rover Sport models when incremental required parts are available for retailers to order.

Many thanks for your cooperation.

Alan K Clarke Senior Engineer, Critical Concerns
Product Investigation, Technical Service
EMAIL: aclark43@jaguarlandrover.com