



**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: US: 24V-234

CAN: 2024-204

Safety Advisory: 24-452

May 1, 2024

SAFETY ADVISORY 24-452

«Dealer_name»
ATTN: Service Manager
«Street»
«Street_2»
«City», «State» «Zip»
«Country»

Dear «Dealer_name»,

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model 2021-2023 Montana, 2021-2022 Montana High Country, 2022-2024 Fuzion, 2021 Cruiser, 2024 Aspen Trail LOFT Fifth Wheels and Travel Trailers. As a result, Keystone RV is conducting a safety recall.

***Reason for
this recall***

It has been decided that the vehicles in the recall population with the Suburban stove LED backlight printed circuit boards (PCB) are not fully coated. The lack of adequate coating in the connection passages between the layers of the PCB can allow liquid from the cooktop surface to accumulate which could result in a short circuit resulting in failure of the PCB. If the PCB fails, it can become overheated and the polyethylene cover of the lights can melt and possibly ignite causing a fire. The vehicles included in the recall are:

Year	Model	Serial Number Ranges
2021-2023	Montana	M4703634 - P4700239
2021-2022	Montana High Country	MA743716 - NA742537
2022-2024	Fuzion	NF810000 - RF810067
2021	Cruiser	M9321337 - M9321881
2024	Aspen Trail LOFT	R8921150 - R8922348

Our records indicate unit(s) sold or in your present lot inventory fall within this range, which will require immediate preventative action. **Important:** If some of the units are still in your inventory, Federal Law requires you to complete the recall service on those units before retail delivery. The unit VIN(s) our records indicate are presently in your inventory or have been sold are as follows:

- | | | | |
|---------|---------|---------|---------|
| «VIN1» | «VIN2» | «VIN3» | «VIN4» |
| «VIN5» | «VIN6» | «VIN7» | «VIN8» |
| «VIN9» | «VIN10» | «VIN11» | «VIN12» |
| «VIN13» | «VIN14» | «VIN15» | «VIN16» |
| «VIN17» | «VIN18» | «VIN19» | «VIN20» |
| «VIN21» | «VIN22» | «VIN23» | «VIN24» |
| «VIN25» | «VIN26» | «VIN27» | «VIN28» |
| «VIN29» | «VIN30» | «VIN31» | «VIN32» |
| «VIN33» | «VIN34» | «VIN35» | «VIN36» |
| «VIN37» | «VIN38» | «VIN39» | «VIN40» |
| «VIN41» | «VIN42» | «VIN43» | «VIN44» |
| «VIN45» | «VIN46» | «VIN47» | «VIN48» |
| «VIN49» | «VIN50» | «VIN51» | «VIN52» |
| «VIN53» | «VIN54» | «VIN55» | «VIN56» |
| «VIN57» | «VIN58» | «VIN59» | «VIN60» |
| «VIN61» | «VIN62» | «VIN63» | «VIN64» |
| «VIN65» | «VIN66» | «VIN67» | «VIN68» |
| «VIN69» | «VIN70» | «VIN71» | «VIN72» |
| «VIN73» | «VIN74» | «VIN75» | «VIN76» |
| «VIN77» | «VIN78» | «VIN79» | «VIN80» |
| «VIN81» | «VIN82» | «VIN83» | «VIN84» |
| «VIN85» | «VIN86» | «VIN87» | «VIN88» |

«VIN89»	«VIN90»	«VIN91»	«VIN92»
«VIN93»	«VIN94»	«VIN95»	«VIN96»
«VIN97»	«VIN98»	«VIN99»	«VIN100»
«VIN101»	«VIN102»	«VIN103»	«VIN104»
«VIN105»	«VIN106»	«VIN107»	«VIN108»
«VIN109»	«VIN110»	«VIN111»	«VIN112»
«VIN113»	«VIN114»	«VIN115»	«VIN116»
«VIN117»	«VIN118»	«VIN119»	«VIN120»
«VIN121»	«VIN122»	«VIN123»	«VIN124»
«VIN125»	«VIN126»	«VIN127»	«VIN128»
«VIN129»	«VIN130»	«VIN131»	«VIN132»
«VIN133»	«VIN134»	«VIN135»	«VIN136»
«VIN137»	«VIN138»	«VIN139»	«VIN140»
«VIN141»	«VIN142»	«VIN143»	«VIN144»
«VIN145»	«VIN146»	«VIN147»	«VIN148»
«VIN149»	«VIN150»	«VIN151»	«VIN152»
«VIN153»	«VIN154»	«VIN155»	«VIN156»
«VIN157»	«VIN158»	«VIN159»	«VIN160»
«VIN161»	«VIN162»	«VIN163»	«VIN164»
«VIN165»	«VIN166»	«VIN167»	«VIN168»
«VIN169»	«VIN170»	«VIN171»	«VIN172»
«VIN173»	«VIN174»	«VIN175»	«VIN176»
«VIN177»	«VIN178»	«VIN179»	«VIN180»
«VIN181»	«VIN182»	«VIN183»	«VIN184»
«VIN185»	«VIN186»	«VIN187»	«VIN188»
«VIN189»	«VIN190»	«VIN191»	«VIN192»
«VIN193»	«VIN194»	«VIN195»	«VIN196»
«VIN197»	«VIN198»	«VIN199»	«VIN200»
«VIN201»	«VIN202»	«VIN203»	«VIN204»
«VIN205»	«VIN206»	«VIN207»	«VIN208»
«VIN209»	«VIN210»	«VIN211»	«VIN212»
«VIN213»	«VIN214»	«VIN215»	«VIN216»
«VIN217»	«VIN218»	«VIN219»	«VIN220»
«VIN221»	«VIN222»	«VIN223»	«VIN224»
«VIN225»	«VIN226»	«VIN227»	«VIN228»
«VIN229»	«VIN230»	«VIN231»	«VIN232»
«VIN233»	«VIN234»		

-- Serial numbers with '*' have been retail sold --

Claims for the units which have been serviced must be submitted. Claims submitted will be used by Keystone to record recall service completions and provide dealer payments. Enclosed is a copy of the Safety Advisory #24-452, which details how to remedy the situation and the proper reimbursement procedures.

We apologize for any inconvenience this situation may cause and greatly appreciate your cooperation. Should you have any questions or concerns regarding this correspondence or the enclosed Safety Advisory, please feel free to contact us.

Sincerely,

KEYSTONE RV COMPANY

cc. National Highway Traffic Safety Administration (NHTSA)
cc. Transport Canada