

Reference Number: GCUS-3-3192

N232431480 - Safety Recall - Front Hub Bearing Bolts Incorrectly Torqued

GENERAL MOTORS

DCS6840

URGENT - DISTRIBUTE IMMEDIATELY

Date: March 28, 2024

Subject: N232431480 - Safety Recall

Front Hub Bearing Bolts Incorrectly Torqued

Models: 2023 Chevrolet Colorado

2023 GMC Canyon

General Motors is releasing Safety Recall N232431480 today.

What Should Dealers Do: Dealers should review IVH or the Dealer Maxis reports for open VINs in their inventory. Dealers can view the attached bulletin and it will also be displayed in Service Information tomorrow.

A Stock VIN list is not included as our records show there are no vehicles in dealer new inventory.

Frequently Asked Questions Document (FAQs)

Attached to this message you will find a document that addresses the most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

END OF MESSAGE