1231 Tech Court Westminster, MD 21157 Phone: (410) 946-1710

Fax: (410) 265-0067 www.frconversions.com



To whom it may concern:

You are receiving this letter to inform you that VIN _____ may be affected by the recent recall we received from Freedman Seating. Attached to this letter are step by step service instructions on how to check if your seat is operating properly.

Should you have any questions please contact Tricia Tarr at 410-946-1710.

Thank you,

Tricia Tarr | Chief Operations Officer

D: 410-946-1710 x117

E: ttarr@frconversions.com
W: www.frconversions.com



The factor of the property of



a a referencia qual da contra e di

the state of the s

State of the series and it requires of the series of the s

.no. Judil

and the state of the energy are applied.

mon misser many mently mon misser many many monopolism many



notice or at all even all



IMPORTANT SAFETY RECALL NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION NHTSA RECALL NO: 24E026

April 1, 2024

FR CONVERSIONS INC ATTN: ELIYAHU ROSENBLOOM 1231 TECH COURT WESTMINSTER, MD 21157

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Freedman Seating Company (FSC) has decided that a defect which relates to motor vehicle safety exists in certain GO-ES Spacesaver Foldaway Seats manufactured between December 11, 2023 and January 31, 2024. The seat back cushion may become disengaged from the dump mechanism when there is a high load applied to the shoulder portion of the seat belt.

Upon receipt of this Recall Notice, FSC is requesting you provide notification of this Product Recall of the subject seats to your Dealer and Customer/Owner.

To correct this condition, we have developed a simple inspection procedure. If the seat does not pass the inspection then there is an easy remedy. A document and video describing the inspection can be found here:

http://www.freedmanseating.com/recall/24e026/

If during the inspection procedure, the seat was found non-compliant, written and video instructions on how to do the repair can be found in the above link. Written instructions are also being sent with this letter.

The repair is expected to take approximately 15 minutes per seat. FSC will reimburse the cost of repairs related to this recall. No parts should be required.



Upon completion of the recall repair work the Customer *must* file a claim with FSC Customer Service for reimbursement referencing FSC Recall #24E026 on the claim.

FSC Recall Contact:
Terry Gogins or Anthony Lee
Customer Service Representative
Freedman Seating Company
4545 W Augusta Blvd
Chicago, IL 60465
800-443-4540
Terry.gogins@freedmanseating.com
Anthony.lee@freedmanseating.com

The form found in the link below must be completed whether repair work was needed or not so that we have a record indicating the vehicle participated in this recall.

http://www.freedmanseating.com/recall/24e026/

Should you have any vehicle(s) in inventory that require recall repair work please make certain these vehicles are corrected prior to sale. 49 CFR 577.13 states it is a violation of Federal law for a manufacturer/dealer to deliver a new motor vehicle covered by this notification under sale or lease until the defect is remedied.

If you have any questions pertaining to this recall, please call FSC Customer Service at 800-443-4540. If your dealer fails or is unable to remedy this defect without charge, or within a reasonable amount of time, you may submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590. You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

Thank you for your prompt review.

David Klopp

Director of Quality, Testing & Compliance Freedman Seating Company Office: 773-524-2440 x241

Dave.klopp@freedmanseating.com



GO-ES SpaceSaver Foldaway Service Instructions

20240130

www.freedmanseating.com










Inspection Step 1


Bring seat back cushion from stowed position (seat back cushion is folded down against seat cushion) to first engagement point of the back lock (most upright position of the seat back cushion)

Add a piece of tape on the dump cover shroud so that it touches the handle



Inspection Step 2

Pull the handle to release the seat back and actuate the back into the most reclined position



© Freedman Seating Company. All rights reserved. Information contained in this document is indicative only. No representation or warranty is given or should be refed on that it is complete or correct or will apply to any particular project. This will depend on the technical and commercial circumstances. It is provided without liability and is subject to change without notice. Reproduction, use or disclosure to third parties, without express written authorization, is strictly prohibited.

3/21/2024

FREEDMAN


4

Inspection Step 3

Release handle and pull seat back forward

If handle returns back to original position, no additional work needed


If handle does not return back to the original position then seat will need to be reworked



© Freedman Seating Company. All rights reserved. Information contained in this document is indicative only. No representation or warranty is given or should be reted on that it is complete or correct or will apply to any particular project. This will depend on the technical and commercial circumstances. It is provided without liability and is subject to change without notice. Reproduction, use or disclosure to third parties, without express written authorization. Is strictly prohibited.

Rework Step 4

Fold the seat back down to the cushion to expose the stop brackets



© Freedman Seating Company, All pigtes is reserved, Information contained in this document is indicative only. No representation or variantly in given or being Company, All pigtes is strength and apply to any particular project. This will depend on the technical and commercial discrimances. It is crowded without faithful and is subject to change without no confidence representations or variances and in company.


3/21/2024

FREEDMAN

6

Rework Step 5

On the stop bracket adjacent to pin, use a Dynafile or similar tool to grind off up to 1/32" off of the face of the stop



© Freedman Seating Company. All rights reserved, Information contained in this document is indicative only. No representation or variantly is given or should be relied on that it is complete or correct or will apply to any particular project. This will depend on the technical and commercial circumstances. It is provided without liability and is subject to change without notion. Reproduction, use or disclosure to third parties, which express written authorization, is stirictly prohibited.

Rework and Final Inspection Step 6

Repeat step 3 to recheck handle and if necessary repeat steps 4-5 to get handle to appropriately lock

3/21/2024





Thank you

Will O'Connor

Lead Engineer - New Product Design (773)-524-2440x321 / Will.OConnor@FreedmanSeating.com







