

AIRSTREAM®

419 W. Pike St., Jackson Center, OH 45334

IMPORTANT SAFETY RECALL

Airstream Interstate Touring Coach

NHTSA 24V-432

Date: 7/9/2024

TO: Airstream Dealer

PROBLEM:

It has come to our attention that certain model year **2024** Interstate touring coaches do not have the 12V in-line fuse that provides back-up power to the water heater/furnace system. If a short circuit were to occur, it could result in a fire, increasing the risk of personal injury and/or property damage.

RANGE OF VEHICLES INVOLVED:

Model year **2024** Interstate touring coaches built between: **March 7, 2024 – March 8, 2024**
Serial Number Range: 311741 & 311743

Following are the affected units:

311741 & 311743

WARRANTY REIMBURSEMENT:

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is .5 hr.

SERVICE ACTION:

The remedy is to install the 12V in-line fuse, per the instructions provided. Please use operation code **TCSBR8932100** when submitting a claim for warranty reimbursement.

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.

encl. – Owners Letter, Repair Procedure



Rick March

General Manager of Airstream Customer Service Group

Re: NHTSA Recall No. 24V-432