

**Daimler Truck
North America LLC**

Daimler Truck North America LLC
Warranty Campaigns Department
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone

DATE: 07/22/2024

TO: My Communication

SUBJECT: SAFETY RECALL NOTICE – STOP DELIVERY: F1005

On **July 3, 2024**, Daimler Truck North America (DTNA) filed a Defect Information Report (DIR) with the National Highway Traffic Safety Administration (NHTSA) and/or a Defect Information Notice (DIN) with Transport Canada (TC) informing the agencies of our intent to conduct a voluntary safety recall.

It is a violation of Federal law for a dealer or distributor to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. **Some of the vehicles subject to this "Stop Delivery Notice" may be in your *new* vehicle inventory.** Until further instructions are available, ***new* vehicles subject to this "Stop Delivery Notice" must be held and not be delivered to customers.**

DTNA strongly recommends that dealers and distributors remedy Recalls before selling used vehicles. For any used vehicle with an open recall not remedied before sale, DTNA requires that the dealer or distributor notify prospective buyers of the open recall.

Please ensure that registration information on vehicles subject to this recall is up to date to facilitate accurate owner notification.

Affected Vehicles in F1005:

Make	Model	Model Yr. Start	Model Yr. End	Prod. Start Date	Prod. End Date
Freightliner	114SD	2025	2025	04/29/2024	06/14/2024
Freightliner	Cascadia	2025	2025	04/30/2024	05/30/2024
Western Star	47X	2025	2025	04/30/2024	06/05/2024
Western Star	49X	2025	2025	05/01/2024	06/11/2024

Problem:

A defect, which relates to motor vehicle safety exists in certain Model Year 2025 Freightliner and Western Star vehicles. The front axles may have been equipped with a tie rod where the ball studs were improperly heat treated which could allow them to crack and break.

Solution:

The complete tie rod assembly will be replaced. Repairs will be performed free of charge by Daimler Truck North America authorized service facilities.

Owner Notification Mailing Schedule: 09/1/2024