

---

**From:** [REDACTED]@hyundaitranslead.com>

**Sent:** Saturday, July 13, 2024 12:11 PM

**To:** [REDACTED]

**Cc:** [REDACTED]

**Subject:** Pitman Arm Nut Technical Service Bulletin Re: [EXTERNAL] Re: Hyundai Steering Gear Box Nut Procedure

**Attachments:** 24-01-059CV - STEERING GEAR PITMAN ARM NUT RETIGHTENING.pdf

**Importance:** High

**CAUTION: This is an external email! STOP, ASSESS, and VERIFY**

Do not click on the links or attachments unless you recognize the sender and trust that the content is safe.  
To report this email as suspicious, please use the Report Phishing Button!

Hello [REDACTED],

Please find attached Hyundai Technical Service Bulletin "STEERING GEAR PITMAN ARM NUT RETIGHTENING (RECALL 264)" as approved and published by HMA.

Kindly proceed immediately with implementing the procedure on all affected units within GET Freight's fleet.

Best regards,

[REDACTED]  
Senior Manager  
Hyundai Eco-Friendly Commercial Vehicles

**Hyundai Translead**