

[Next Unread Message](#)

[View Message](#)

Sent on	02	25	2025	Expires on	04	16	2025
From	Motorcycle Service National						
Subject	Revised: NCW50 #1 - Inspection Kit Update						

February 25, 2025

Re: **NCW50 Metropolitan Transmission Case Oil Leak Safety Recall**

Dear Honda Dealer:

American Honda has identified a potential parts concern affecting the NCW50 Metropolitan Safety Recall for a transmission case oil leak (NCW50 Service Bulletin #1).

The sandpaper discs included in the Inspection Kit (06114-GGZ-315) may be missing from some kits. Since many affected units will not require the transmission case to be resurfaced, dealers will likely have unused discs from other kits to use in case the discs are missing in an Inspection Kit.

If an Inspection kit is missing the sandpaper discs and your dealership has no new, unused discs available, [CLICK HERE](#) for instructions to make new sandpaper discs

If you have any questions, please contact AHM *TechLine* through *TechLine Connect* on *iN*.

Sincerely,

American Honda Motor Co., Inc.

Powersports Division