

[Next Unread Message](#)

[View Message](#)

<b>Sent on</b>	12	17	2024	<b>Expires on</b>	02	23	2025
<b>From</b>	Powersports Service Publications						
<b>Subject</b>	REVISED SAFETY RECALL: CBR600RR/RA 2007-2017 Fuel Pump Inspection/Replacement						

You were notified on December 5 of a **SAFETY RECALL CAMPAIGN** on **CERTAIN** 2007, 2009 – 2017 model year CBR600RR/RA motorcycles to inspect and, if necessary, replace the fuel pump assembly is now available on **iN**.

An update has been made to the *Fuel Pump Inspection* section of the bulletin to correct the fuel pump lot code range. Please refer to the revised service bulletin for details.

Service Bulletin CBR600 #3, which includes all the information relating to this SAFETY RECALL Campaign, can be found on *iN* by navigating to

***Service > Service Publications > Service Bulletins.***

**Make sure all departments in your dealership are aware of this SAFETY RECALL Campaign.**

If you have any questions, please contact *AHM TechLine* through *TechLine Connect* on ***iN***.

Sincerely,

American Honda Motor Co., Inc.

Powersports Division

MTB 55278-B (2412)