

[Next Unread Message](#)

[View Message](#)

Sent on	11	13	2024	Expires on	12	31 2024
From	Powersports Service Publications					
Subject	STOP SALE NOTICE: 2010, 2012, 2013 VFR1200F/FD SAFETY RECALL					

Click [here](#) to view in PDF format.

Dear Honda Dealer:

Honda is issuing a **STOP SALE NOTICE** on dealer parts inventory of replacement fuel pumps (P/N 16700- MGE-013) that can be installed on **CERTAIN** 2010, 2012, and 2013 VFR1200F/FD motorcycles. Due to a manufacturing defect, the rubber impeller inside the fuel pump can warp or swell when exposed to fuel, causing the impeller to lock in place and prevent fuel flow to the engine. A locked impeller can cause the engine to stall without warning while riding. Effective immediately, you MUST NOT SELL any affected replacement fuel pump with a P/N of 16700-MGE-013.

AFFECTED UNITS

ALL replacement fuel pumps in dealer parts inventory with part number **16700-MGE-013**

SERVICE BULLETIN

Service Bulletin: VFR1200F/FD motorcycle #1, which includes all the information relating to this Safety Recall, is expected to be issued in November 2024.

PARTS INFORMATION

Replacement fuel pump kits to repair affected motorcycles will be available soon. Dealers will be notified when parts become available.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected 2010, 2012, 2013 VFR1200F/FD motorcycles in January 2025. Customers will be informed that their motorcycle may be affected by a safety related defect and will be advised to make an appointment with an authorized Honda dealer for repair.

Make Sure All Departments In Your Dealership Are Aware Of This Safety Recall.

If you have any questions, please contact AHM TechLine through TechLine Connect on **iN**.

Sincerely,

American Honda Motor Co., Inc.

Powersports Division