

[Next Unread Message](#)

[View Message](#)

Sent on	12	13	2024	Expires on	02	19	2025
From	Powersports Service Publications						
Subject	SAFETY RECALL: VFR1200F/FD 10-13 Fuel Pump Inspection/Replacement (VFR1200 #1)						

The Service Bulletin supporting the **SAFETY RECALL CAMPAIGN** on **CERTAIN** 2010, 2012, 2013 model year VRF1200F/FD motorcycles to inspect, and if necessary, replace the fuel pump assembly is now available on *iN*.

Service Bulletin VFR1200 #1, which includes all the information relating to this SAFETY RECALL Campaign, can be found on *iN* by navigating to

Service > Service Publications > Service Bulletins.

Make sure all departments in your dealership are aware of this SAFETY RECALL Campaign.

If you have any questions, please contact *AHM TechLine* through *TechLine Connect* on *iN*.

Sincerely,

American Honda Motor Co., Inc.
Powersports Division

MTB 55276 (2412)