

NHTSA Recall Number: 24V-113 Honda Campaign Number: KQ1A/KQ1B Service Bulletin Number: MTB55163C

## IMPORTANT SAFETY RECALL

This notice applies to your vehicle:

June 2024

Dear

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. It is a follow-up to the original notice sent to you in April 2024. Honda has decided that a defect which relates to motor vehicle safety exists in certain 2020-2024 GL1800/Goldwing motorcycles.

Why my vehicle is under recall: The fuel pump module may have an improperly molded impeller. Over time the impeller can deform and cause the fuel pump to become inoperable.

## Safety Consequence

An inoperable fuel pump could prevent an engine from starting, cause a motorcycle to lose drive power or stall while riding, increasing the risk of a crash or injury.

What Honda will do:

The replacement parts needed to repair your motorcycle are now available. Your Honda Powersports dealer will inspect and if necessary replace the fuel pump for FREE. Honda estimates that the repair will take approximately 1 hour to complete. However, your dealer can provide you with a better estimate of the overall time for this service visit, as it may be necessary to make your vehicle available for a longer period of time.

What we need you to do:

Please call any authorized Honda Powersports dealer and schedule an appointment to have your vehicle repaired for FREE. If you have already had your vehicle inspected and it did not require fuel pump module replacement, no further action is necessary.

If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

## California Owners Only

The DMV will not renew your motorcycle's registration until this emissions recall has been completed. After completing the repair procedure, your dealer will give you a Vehicle Emission Recall - Proof of Correction certificate. Please make sure the dealer completes and provides you the certificate. Keep the certificate for your records as proof that the emissions recall was completed. Submit the certificate to the DMV only if the DMV requests it.

- Check recall information for your motorcycle by accessing the Honda recall lookup tool at https://powersports.honda.com/recalls and entering your Vehicle Identification Number (VIN).
- If you have questions or concerns, we encourage you to:
  - visit https://powersports.honda.com/recalls: or
  - o contact your local Honda Powersports dealer; or
  - $_{\odot}\,$  send Customer Relations a message via https://powersports.honda.com/contact-us; or
  - o call American Honda's Powersports Customer Relations at 1-866-784-1870 Monday through Friday, 8:30 a.m. to 4:30 p.m., Pacific Time.

If you paid out of pocket to have these specific recall repairs performed on your vehicle, you may be eligible for reimbursement; please contact American Honda's Powersports Customer Relations at 1-866-784-1870 to determine potential eligibility and for instructions on how to request reimbursement.

If you no longer own this vehicle or if any of the information is not correct, please complete and return the enclosed prepaid Information Change Card as soon as possible. If you are a lessor of this vehicle, federal regulations require you to forward this notice to your lessee within ten days.

If you believe that American Honda or the dealer has failed or is unable to remedy the defect in your vehicle, without charge and within a reasonable period of time (60 days from the date you first contact the dealer for a repair appointment), you may submit a complaint to the Administrator, National Highway Traffic Safety Administration (NHTSA), 1200 New Jersey Ave., SE, Washington, DC 20590. Alternatively, you may call the NHTSA toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153) or go to http://www.safercar.gov.

We sincerely apologize for any inconvenience this recall may cause, but please be assured that your safety is our first concern.

Sincerely,

American Honda Motor Co., Inc.

