

# RECALL NOTICE



1

Subject: 24KWD: T370 / T440 / T470 / T480 / T660 / T680 / T800 / T880 / W900 / C500 Air Tank Reservoir Volume Non-Compliance



## IMPORTANT SAFETY RECALL



**A PACCAR COMPANY**  
Customer Service Department  
Kenworth Truck Company  
P.O. Box 1000  
Kirkland, Washington 98083-1000



U.S. Department of  
Transportation

Issued in Accordance  
With Federal Law



www.nhtsa.gov

**IMPORTANT SAFETY RECALL INFORMATION**

FIRST-CLASS MAIL  
US POSTAGE  
PAID  
SEATTLE, WA  
PERMIT NO. 2389

October 23, 2025

## **IMPORTANT SAFETY RECALL**

This notice applies to your vehicle: VIN: [REDACTED]

**This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.**

Subject: 24KWD: T370 / T440 / T470 / T480 / T660 / T680 / T800 / T880 / W900 / C500 Air Tank Reservoir Volume Non-Compliance  
NHTSA Recall number: 24V145  
Expiration Date: None



Dear Kenworth Customer,

Kenworth Truck Company has decided that certain model year 2009-2024 T370 / T440 / T470 / T480 / T660 / T680 / T800 / T880 / W900 / C500 vehicles manufactured between 01/08/2008 and 10/26/2023 fail to conform to Federal Motor Safety Standard (FMVSS) No. No.121 Air Brake Systems.

These vehicles may have air tank reservoirs with less than twelve times the combined volume of all service brake chambers, which could reduce braking capacity in an emergency and may increase the risk of a crash. An audible alarm and warning light in the dash will warn the operator if pressure in the air system is low.

<b>What is the problem?</b>	Air tank reservoir does not comply with FMVSS 121.
<b>What will your dealer do?</b>	Dealers will install an additional air tank to meet air volume requirements.
<b>What you must do ...</b>	Contact your dealer immediately to schedule a repair.

Kenworth will repair this defect at no charge to you. To locate your nearest Kenworth dealer, please scan the QR code at the top of this letter or use "Dealer Locator" at [www.Kenworth.com](http://www.Kenworth.com) When scheduling this repair, please refer to recall 24KWD and the VIN(s) listed in this letter. This repair may require up to 4 hours of labor. You may be eligible for reimbursement if you performed this repair before receiving notification of the recall. For more information, please e-mail [servicebulletins@paccar.com](mailto:servicebulletins@paccar.com).

If you believe this remedy was not available to you within a reasonable amount of time and free of charge, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590; call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or visit <http://www.safercar.gov>.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to [servicebulletins@paccar.com](mailto:servicebulletins@paccar.com).

We appreciate your attention to this matter and value your loyalty to Kenworth and its dealer network.

Kenworth Truck Company