



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Hoster Way North
 Renton, WA 98057
 (425) 828-5888

A PACCAR COMPANY

IMPORTANT SAFETY RECALL INFORMATION




Issued in Accordance
 With Federal Law



PRESORTED
 FIRST-CLASS MAIL
 U.S. POSTAGE PAID
 CLEVELAND, OH
 Permit No. 488

SAFETY RECALL



*****AUTO**MIXED AADC 440



000084
 T2 P1

24PBE

SAFETY RECALL

Recall Notice: 24PBE

December 12, 2025
Subject: 24PBE: Kongsberg Automotive Right-Hand Shift Stalk
NHTSA: 24V190
Expiration Date: None



IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s) with VIN(s) listed at the bottom or back of this page.

Dear Peterbilt Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in certain model year 2021-2024 365, 367, 389, 535, 536, 537, 548, 567, and 579 chassis manufactured between 11/09/2020 and 12/23/2022 with right-hand shift stalk part numbers Q21-6155-211, Q21-6155-213, Q21-6155-214, Q21-6164-111, or Q21-6165-113.

What is the problem?	The right-hand shift stalk may have an improper wire harness terminal crimp within the wire harness connector. Loss of communication between the right-hand shift stalk and the vehicle could disable the vehicle after it comes to a stop, which may increase the risk of a crash.
What will your dealer do?	Dealers will replace the right-hand shift stalk with a new part, free of charge.
What should you do?	Contact your dealer immediately to schedule a repair. This repair may require up to 1 hour of labor.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at www.Peterbilt.com. When scheduling this repair, please refer to recall 24PBE: Kongsberg Automotive Right-Hand Shift Stalk and the VIN(s) listed in this letter. You may be eligible for reimbursement if you performed this repair before receiving notification of the recall. For more information, please e-mail servicebulletins@PACCAR.com.

If you believe this remedy was not available to you within a reasonable amount of time and free of charge, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590; call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or visit <http://www.safercar.gov>.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

We appreciate your attention to this matter and value your loyalty to Peterbilt and its dealer network.

Sincerely,

Peterbilt Motors Company

Our records indicate that these vehicles are affected by 24PBE and are owned by [REDACTED]

