

IMPORTANT SAFETY RECALL

Expedition date

Corporate Name

Civic number

City, Province, Zip Code

This notice applies to your vehicle(s):

See appendix A

Notice of Defect R2024-009 – Parking Brake Secondary Latch

This notice is sent to you in accordance with the *National Traffic and Motor Vehicle Safety Act*. Lion Electric has decided that a defect which relates to motor vehicle safety exists in certain 2024-2025 LionC vehicles.

Description of the vehicle(s) affected by the defect

Make	Lion
Model	Lion C
Model year	2024-2025
NHTSA Recall Number	24V-377

Description of the defect

The parking brake levers supplied by *Orscheln Product L.L.C.* may contain a manufacturing defect. Defective levers can be disengaged by applying force to the lever without pressing the release button. The secondary latch that holds the lever in place when it is in the applied position may not engage. A brake lever exhibiting the concern will still engage the park brake in the applied lever position.

Description of the safety risk

The parking brake lever could be accidentally deactivated. Without the parking brake, the vehicle may start to move. Unexpected vehicle movement increases the risk of a crash or injury.

Corrective measures and precautions

As a precautionary measure, customers must perform the verification procedure "Inspection Bulletin IB-0379" attached to this notice to validate if your vehicle is impacted by this defect. If your inspection fails, please contact Lion at the number below to schedule a repair. If your inspection passes, please follow the instructions in the inspection procedure to claim your inspection time and send Lion the



necessary information to declare this defect closed. The inspection reimbursement is set at 15 minutes per vehicle at the standard warranty labor rate as per Lion's Standard Limited Warranty.

If the parking brake lever on your vehicle is affected by this defect, please make an appointment to have your parking brake lever replaced, which will be performed at Lion's expense by one of Lion's technicians. The repair solution is available immediately and we estimate that the work to correct the defect will take approximately 1.5 hours.

Contact

For any questions, do not hesitate to contact the service department at 1-855-546-6706, ext. 229.

If you have already paid to have your vehicle repaired for this defect, you may be eligible for reimbursement of the charges incurred for the repair or replacement, as applicable. To learn more about what you need to do to obtain reimbursement, contact Lion's Customer Support at the number indicated above.

If you are no longer the owner of the vehicle, please contact Lion to provide the new owner's information. Lion will then contact the new owner.

If you are the current owner and are leasing the vehicle, please forward a copy of this notice to the lessee within 10 business days of the date of receipt of this notice to comply with U.S. federal regulations.

After contacting Lion's Customer Service Department, if you still are not able to have the safety defect remedied without charge and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Our priority is to provide you with a product of the utmost quality and safety. We apologize for the inconvenience and thank you for your trust and valuable cooperation.

Michael Bianco, Eng.
Director, Service Engineering