



IMPORTANT SAFETY RECALL

This notice applies to your vehicle,

October 24, 2024

SAFETY RECALL N927: Near Field Sensor Module Overheat – Camera Image Unavailable

Vehicles Affected: 2024MY Range Rover, Range Rover Sport, Discovery Sport, Range Rover Evoque, Range Rover Velar, Defender

National Highway Traffic Safety Administration (NHTSA) Recall Number: 24V-678

Dear Land Rover Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Land Rover has decided that a defect which relates to motor vehicle safety exists in certain vehicles listed above.

Your vehicle is included in this Recall action.

What is the reason for this program?

The Near Field Sensing Module (NFSM) may overheat and cause the 3D surround camera images, including the rearview camera image, not to display.

A rearview camera image that does not display can decrease the driver's visibility, increasing the risk of injury or crash.

What are the warning signs of this condition?

In the event of this issue occurring, no camera images will be shown on the center touchscreen display, an error message will be shown instead.

Are there any precautions that may be taken to minimize the safety risk until the corrective measures are implemented?

Should there be any camera display error shown in the center touchscreen, drivers are requested to take extra care when reversing or parking their vehicles. Parking distance sensors may continue to operate.

What will Land Rover and your authorized Land Rover Retailer do?

An authorized Land Rover retailer will replace and reconfigure the Near Field Sensing Module (NFSM). There will be no charge to the owners for this repair.

What should you do?

Please contact your preferred authorized Land Rover retailer and provide them with your Vehicle Identification Number (VIN) and request a service date to complete the work required under Program Code 'N927'.

Attention Leasing Agencies: If you are a vehicle lessor, Federal Regulations require you to forward this notice to your lessee within TEN (10) days.



0000038
0000001

How long will it take?

The work will be carried out as quickly and efficiently as possible in order to minimize any inconvenience to customers and is expected to take no longer than 2 hours. Your retailer can provide you with a better estimate of the overall time for the service visit.

What if I have previously paid for this concern?

If you have already paid for this concern before the date of this letter, Land Rover is offering a refund. To qualify for a refund, during the recall repair service appointment, please provide your authorized Jaguar retailer with the original paid receipt.

To avoid delays, please do not send the receipt to Jaguar Land Rover North America, LLC.

Moved or no longer own this Land Rover vehicle?

If you are no longer the owner of this vehicle, Land Rover would appreciate the name and address of the new owner (if known); please fill out and return the enclosed return postage-paid card.

What should you do if you have further questions?

If you have any questions or concerns regarding this Program, please contact the Service Manager at your authorized Land Rover retailer for assistance. If you have any queries or concerns that your local Retailer cannot address, please contact the Land Rover Customer Relationship Centre at 1-800-637-6837, **option 9**, and one of our representatives will be happy to assist you.

You may also contact us by email using the following address: lrweb2@jaguarlandrover.com. Please include your full name, address, and VIN of your vehicle in your email.

If you have the need to contact Land Rover by mail, please use the following address:

Jaguar Land Rover North America, LLC
ATTN: Customer Relationship Center
100 Jaguar Land Rover Way
Mahwah, NJ 07495

If your retailer fails or is unable to remedy this defect without charge and within a reasonable amount of time, you may submit a complaint to the:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Or call the toll-free Vehicle Safety Hotline at **888-327-4236 (TTY: 800-424-9153)**; or go to <http://www.safercar.gov>.

Land Rover appreciates your confidence in our product and wish to do everything we can to retain that confidence. We recognize this service visit may be an inconvenience to you. Land Rover, in cooperation with your authorized Land Rover retailer, will strive to minimize any inconvenience to you caused by this program.

Sincerely,



Wayne Clarke
Director, Technical Services
Jaguar Land Rover, NA LLC