



Elgin Sweeper Company

1300 W. Bartlett Rd

Elgin, Illinois 60120

847.741.5370

elginsweeper.com

“IMPORTANT SAFETY RECALL”

“This notice applies to your vehicle,

October 29, 2024

Customer name

Customer Address 1

Customer Address 2

VIN

NHTSA RECALL No. 24V-692Dear Elgin Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Elgin Sweeper Company Inc. has decided that a defect, which relates to motor vehicle safety, exists in some 2023-2024 CJ Broom Badgers mounted on Isuzu chassis.

REASON FOR RECALL

The fuel tank system originally used on the Broom Bader CJ may not meet the requirements of 49 CFR Part 393.67. The original fuel tank fill system may allow the tank to be filled to more than 95% of its volume. There is a possibility that a fuel leak, increasing the risk of a fire

WHAT WE WILL DO

A safety recall has been issued for Broom Badger CJ models manufactured between May 5th, 2023, and May 30th, 2024. Elgin Sweeper Company will repair this defect free of charge. We will install FSO kit 1144147 to prevent overfilling of the Isuzu NRR fuel tank. The repair consists of replacing the vent tube, barbed fitting, a hose, a decal, and cable ties. The repair will take approximately XX Hours and/or XX minutes.

WHAT YOU SHOULD DO

Please contact your Elgin Dealer as soon as possible to arrange a service date so the dealer may schedule the repair. Instructions for making this repair have been sent to your dealer and the parts are available. Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

Your Elgin Dealer is best equipped to obtain parts and provide service to ensure that your Elgin Street sweeper is repaired as promptly as possible. If, however, you take your unit to your dealer on the agreed service date, and they do not remedy this condition within six (6) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374). If you believe you are eligible for reimbursement of costs that you incurred to repair this defect during the time period listed above, you may submit a reimbursement claim to your local Elgin Sweeper Distributor via mail.

If you no longer own this sweeper, please fill out the included postcard with change of ownership information and mail back to Elgin Sweeper Company.

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Chris Armbruster
Sr. Service Manager
Elgin Sweeper Company



Elgin Sweeper Company

1300 W. Bartlett Rd

Elgin, Illinois 60120

847.741.5370

elginsweeper.com

“IMPORTANT SAFETY RECALL”

“This notice applies to your vehicle,

October , 2024

Customer name

Customer Address 1

Customer Address 2

VIN

Units Affected: CJ Broom Badger Models manufactured between May 5th, 2023, and May 30th, 2024

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Elgin Sweeper Company Inc. has decided that a defect, which relates to motor vehicle safety, exists in some CJ Broom Badgers mounted on Isuzu chassis.

REASON FOR RECALL

The fuel tank system originally used on the Broom Bader CJ may not meet the requirements of 49 CFR Part 393.67. The original fuel tank fill system may allow the tank to be filled to more than 95% of its volume. There is a possibility that a fuel leak could contribute to a fire

WHAT WE WILL DO

A safety recall has been issued for Broom Badger CJ models manufactured between May 5th, 2023, and May 30th, 2024. Elgin Sweeper Company will repair this defect free of charge. We will install FSO kit 1144147 to prevent overfilling of the Isuzu NRR fuel tank.

WHAT YOU SHOULD DO

Please contact your Elgin Dealer as soon as possible to arrange a service date so the dealer may schedule the repair. Instructions for making this repair have been sent to your dealer and the parts are available. Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

Your Elgin Dealer is best equipped to obtain parts and provide service to ensure that your Elgin Street sweeper is repaired as promptly as possible. If, however, you take your unit to your dealer on the agreed service date, and they do not remedy this condition within six (6) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374). If you believe you are eligible for reimbursement of costs that you incurred to repair this defect during the time period listed above, you may submit a reimbursement claim to your local Elgin Sweeper Distributor via mail.

If you no longer own this sweeper, please fill out the included postcard with change of ownership information and mail back to Elgin Sweeper Company.

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Chris Armbruster
Sr. Service Manager
Elgin Sweeper Company