



IMPORTANT SAFETY RECALL

Indian Motorcycle
Company
P.O. Box 47700
Medina, MN 55340-9960

This notice applies to your vehicle
Recall Campaign: **24V-860**
Subject: **2022 FTR Fuel Tank Replacement**
PLEASE READ IMMEDIATELY

VIN: I-24-09
First Name Last Name
Address
City, State ZIP

Dear Indian Motorcycle Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

The reason for this notice:

Indian Motorcycle has determined that a defect which relates to motor vehicle safety exists in 2022 FTR motorcycles.

A small number of motorcycles may have been assembled with a fuel tank that may leak. If this occurs, fuel may flow in close proximity to a heat source, posing a fire hazard and risk of serious injury.

What you should do:

Contact your authorized Indian Motorcycle dealer to schedule an appointment to have the repairs performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Indian Motorcycle dealer. When making contact with your dealer, discuss parts availability, their schedule and how long they will need to keep your vehicle.

What your dealership will do:

To address this concern, Polaris has authorized your dealer to install a new fuel tank. This work will be performed by your dealer at no cost to you.

This notice was mailed to you according to our most current registration information. If you no longer own this vehicle, or if some of the contact information in this notice is incorrect, please contact your dealer to complete a transfer of ownership. Federal law requires that any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within 10 working days after the day on which the notice is received.

If you need assistance contacting or locating an Indian Motorcycle dealer, or if you have questions your Indian Motorcycle dealer is not able to address, contact our Indian Motorcycle Owner Connections Department at 1-877-204-3697, scan the QR code, or go to <https://www.polaris.com/en-us/help-center/>.



If you previously paid for repair(s) to your vehicle for this specific condition prior to receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information regarding obtaining reimbursement please contact your Indian Motorcycle Dealer or Indian Motorcycle Owner Connections Department using the contact information above.

If you believe that Indian Motorcycle has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or on the web go to www.nhtsa.gov.

We apologize for this inconvenience and assure you that we are committed to customer satisfaction and providing world-class products for riders to enjoy.

Sincerely,

Indian Motorcycle Company

For the latest updates to this safety recall, or to check if your vehicle is part of another safety recall, scan the QR code, or go to www.polaris.com/en-us/on-road-recalls/.

