



American Honda Motor Co., Inc.
4900 Marconi Dr.
Alpharetta, GA 30005-8847
Phone (866) 784-1870

NHTSA Recall Number: 24V-864
Honda Campaign Number: KR2
Service Bulletin Number: 55278

IMPORTANT SAFETY RECALL

This notice applies to your vehicle: [REDACTED]

December 2024

Dear [REDACTED]

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Honda has decided that a defect which relates to motor vehicle safety exists in certain 2007, 2009 – 2017 CBR600RR motorcycles.

Why my vehicle is under recall: The fuel pump module installed as a service part on your vehicle may have an improperly molded impeller. Over time the impeller can deform and cause the fuel pump to become inoperable.

Safety Consequence

An inoperable fuel pump could prevent an engine from starting, cause a vehicle lose drive power or stall while driven, increasing the risk of a crash or injury.

What Honda will do:

Your Honda Powersports dealer will inspect and replace the fuel pump module, if necessary, for **FREE**. Honda estimates that the repair may take approximately 1 hour to complete. However, your dealer can provide you with a better estimate of the overall time for this service visit, as it may be necessary to make your vehicle available for a longer period of time.

What we need you to do:

Please call any authorized Honda Powersports dealer and schedule an appointment to have your vehicle repaired for **FREE**.

If you are not the only rider of this vehicle, please advise all other riders and passengers of this important information.

California Owners Only

The DMV will not renew your vehicle's registration until this recall has been completed. After completing the repair procedure, your dealer will give you a Vehicle Emission Recall - Proof of Correction certificate. Please make sure the dealer provides you with a completed certificate. Keep the certificate for your records as proof that the recall was completed. Submit the certificate to the DMV only if the DMV requests it.

Emission Warranty

In order to ensure your full protection under the emission warranty provisions, it is recommended that you have your vehicle repaired as soon as possible. Failure to do so could be determined as lack of proper maintenance.

- Check recall information for your motorcycle by accessing the Honda recall lookup tool at <https://powersports.honda.com/recalls> and entering your Vehicle Identification Number (VIN).
- If you have questions or concerns, we encourage you to:
 - visit <https://powersports.honda.com/recalls>; or
 - contact your local Honda Powersports dealer; or
 - send Customer Relations a message via <https://powersports.honda.com/contact-us>; or
 - call American Honda's Powersports Customer Relations at 1-866-784-1870 Monday through Friday, 8:30 a.m. to 4:30 p.m., Pacific Time.

If you paid out of pocket to have these specific recall repairs performed on your vehicle, you may be eligible for reimbursement; please contact American Honda's Powersports Customer Relations at 1-866-784-1870 to determine potential eligibility and for instructions on how to request reimbursement.

If you no longer own this vehicle or if any of the information is not correct, please complete and return the enclosed prepaid Information Change Card as soon as possible. If you are a lessor of this vehicle, federal regulations require you to forward this notice to your lessee within ten days.

If you believe that American Honda or the dealer has failed or is unable to remedy the defect in your vehicle, without charge and within a reasonable period of time (60 days from the date you first contact the dealer for a repair appointment), you may submit a complaint to the Administrator, National Highway Traffic Safety Administration (NHTSA), 1200 New Jersey Ave., SE, Washington, DC 20590. Alternatively, you may call the NHTSA toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153) or go to <http://www.safercar.gov>.

We sincerely apologize for any inconvenience this recall may cause, but please be assured that your safety is our first concern.

Sincerely,

American Honda Motor Co., Inc.



0014283
0000001