



1 Tesla Rd.
Austin, TX 78725

February 5, 2025

Tesla will not be sending a 49 C.F.R Part 577 owner notification letter to owners of the 25 vehicles affected by 24V-904/SB-24-00-017. Beginning on or shortly after August 16, 2024, affected vehicles received an over-the-air software remedy that addressed the non-compliance that is the subject of this recall. The remedy software was installed on each of the 25 recalled vehicles between August 27, 2024, and September 17, 2024. Every affected vehicle installed the remedy software prior to the 60-day notification deadline. The Safety Act does not require an owner notification letter when the vehicle has already been remedied.