

RECALL 24V325 REMEDY INSTRUCTIONS



Make(s): AURORA
Model(s): ART26BHS
Model Year(s): 2024

Concern:
The breakaway switch may not be correctly wired to constant hot. This condition may lead to the failure of the brake-away switch to activate in an emergency.

Repair Code: RC-036-22-00-004536
Allotted Time: .30 HRS.
Inspection Code: N/A
Allotted Time: N/A
Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: N/A
Part(s) Return: N/A

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

STEP 1: TRACE THE BLACK WIRE FROM THE BREAKAWAY SWITCH INTO THE 4"X4" JUNCTION BOX;

- FIND IT TERMINATED INTO A WAGO CONNECTOR WITH A PURPLE WIRE

STEP 2: REMOVE THE BLACK WIRE FROM THE WAGO AND PULL THE BLACK WIRE FROM THE JUNCTION BOX;

STEP 3: REMOVE THE BATTERY DISCONNECT SWITCH COVER;

STEP 4: STRIP THE BLACK WIRE AND CRIMP THE APPROPRIETE SIZE RING TEMERINAL (THAT FITS THE BATTERY DISCONNECT STUD);

STEP 5: REMOVE THE NUT ON THE BATTERY DISCONNECT CONSTANT HOT SIDE (FROM THE BATTERY);

STEP 6: INSTALL THE BREAKAWAYS BLACK WIRE WITH NEW RING TERMINAL TO THE CONSTANT HOT (FROM THE BATTERY);


- TIGHTEN THE NUT BACK DOWN ON THE CONTACT HOT SIDE;
- REINSTALL THE BATTERY DISCONNECT SWITCH COVER;

STEP 7: TUCK ALL WIRING BACK INSIDE THE 4"X4" JUNCTION BOX AND SECURE THE COVER BACK ON;

STEP 8: TEST FOR PROPER FUNCTIONALITY;

STEP 9: CLAIM REPAIR CODE.

JUNCTION BOX



NEWLY ROUTED SWITCH

