



## Thor Motor Coach Recall Repair Instructions

Recall #	<b>24V-427 2024-417</b>		
Description/Title:	<b>Power sofa breaker</b>		
Affected Product Line(s):	<b>Certain 2025 Tranquility, Sanctuary</b>		
Service Campaign # :	<b>RC000305</b>		
Repair Code:	<b>Inspect Only: TMCRC10114V  Inspect with Repair: TMCRC10115V</b>	Released Date:	<b>7/22/2024</b>
Time Allowed:	<b>Inspect Only: 0.1  Inspect with Repair: 0.3</b>	Document Revision:	<b>A</b>

### Issue:

It has been discovered that Certain Model Year 2025 Tranquility & Sanctuary motorhomes may have the incorrect size power sofa breaker installed. During production, the power sofa breaker installed may be a 50amp breaker when a 20amp breaker is required. The wiring connected to the breaker can overheat, which could lead to melting and the potential for a fire.

### Tools:

Socket and ratchet

### Parts:

**TMC Recall Part # 0100800**





# Thor Motor Coach Recall Repair Instructions

## Instructions:

### Inspection:

1. The breaker is located underneath the kitchen sink.



### 12V BREAKERS

NO	GA	COLOR	AMPS	POWER TO
	10	RED	20	SOFA

2. If the breaker is 50amp, it will need to be replaced with a 20amp breaker. Continue to Step 3.



## Thor Motor Coach Recall Repair Instructions

If the motorhome has the correct 20amp breaker installed, the inspection is complete.  
No repair is required.

### **Repair:**

3. Unplug the coach and turn off the inverter.
4. Disconnect the ground cable from the house battery.
5. Remove the 50amp breaker and replace with 20amp breaker.
6. Reconnect the ground cable to the house battery.
7. Plug the coach back in.