


RECALL 24V775 / 2024-612 REMEDY INSTRUCTIONS

 FOREST RIVER	Make(s): AURORA & CATALINA Model(s): ART26BHS & CAT261BHS Model Year(s): 2024 - 2025	Repair Code: RC-632-09-00-004620 Allotted Time: 1.00 HRS. Inspection Code: RC-632-05-00-004619 Allotted Time: .10 HRS.
	Concern: The washer prep may not have an anti-siphon vent installed.	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: F100670980 Part(s) Return: N/A

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

INSPECTION:

STEP 1: INSPECT WASHER PREP FOR ANTI-SIPHON VENT;

- IF ANTI-SIPHON VENT IS PRESENT, CLAIM INSPECTION CODE;
- IF ANTI-SIPHON VENT IS NOT PRESENT, MOVE TO REMEDY;

REMEDY:

STEP 1: REMOVE ACCESS PANEL IN PANTRY;

STEP 2: REMOVE 11 - ½ INCHES FROM THE BLACK PIPE;

STEP 3: PLACE MALE ADAPTER ON THE TOP OF THE HEPA/ANTI-SIPHON VALVE;

STEP 4: ADD 5-INCH PIECE OF BLACK PIPE TO MALE ADAPTER;

STEP 5: PLACE FEMALE ADAPTER ON THE BOTTOM OF THE HEPA/ANTI-SIPHON VALVE;

STEP 6: PREP THE PIPE SURFACE;

STEP 7: GLUE HEPA/ANTI-SIPHON FITTING TO BLACK PIPE;

STEP 8: REPLACE ACCESS PANEL;

STEP 9: CLEAN AND CLAIM REPAIR CODE.