


## RECALL 24V803 REMEDY INSTRUCTIONS

 <b>FOREST RIVER</b>	Make(s): PALOMINO Model(s): PAT2085BHS Model Year(s): 2025	Repair Code: RC-026-13-00-004624 Allotted Time: .50 HRS. Inspection Code: N/A Allotted Time: N/A
	Concern: The LP Gas manifold block may be installed in the jounce path of the axles' equalizer.	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: N/A Part(s) Return: N/A

**Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.**

STEP 1: LOCATE THE LPG MANIFOLD WITH QUICK DISCONNECT NEXT TO THE CENTER AXLE HANGER;

STEP 2: REMOVE FASTENERS FROM LPG MANIFOLD AND MOVE THE MANIFOLD TO 5" FROM THE CENTER AXLE HANGER;

- ENSURE THE QUICK DISCONNECT IS STILL ASSESSABLE;

STEP 3: REINSTALL THE FASTENERS, OR USE NEW;


STEP 4: CLAIM REPAIR CODE.

**SEE THE ATTACHED FOR REFERENCE ONLY.**

PICTURES TO THE RIGHT ARE THE REPAIR EXAMPLES GAS LINE, MANIBLOCK AND RVQ-DISCONNECT MUST BE 5" FORWARD FROM CENTER AXLE HANGER TO PROVIDE ENOUGH CLEARANCE FROM EQUALIZER FAILURE TO DO SO MAY RESULT IN 1 OR MORE OF THE GAS LINE PARTS TO BE CRUSHED



MANIBLOCK AND HOSE MUST BE 5" FORWARD FROM CENTER AXLE HANGER



PICTURE BELOW SHOWS THE EQUALIZER BEING BELOW THE GAS LINE WHEN GOING OVER A CURB OR POTHOLE IT MAY CAUSE IT TO CRUSH THE GASLINE

