

SAFETY AND EMISSIONS RECALL 7024J  
REPAIR PROCEDURE START PAGE

To begin repairing campaign 7024J, you must follow the steps below.

1. Please identify the model of vehicle, PHEV or MHEV. The vehicle can be identified by the logo on the left front fender, which states "PHEV" or "INLINE 6" (MHEV).



**THE MODEL MUST MATCH THE PROCEDURE. DO NOT UPDATE MODULES IN A DIFFERENT PROCEDURE. IF THE WRONG PROCEDURE IS USED, THIS IS AN IMPROPER REPAIR AND THE WARRANTY CLAIM WILL BE REJECTED, CAUSING CUSTOMER FRUSTRATION IN RETURNING UNNECESSARILY FOR A REPEAT REPAIR AND A POOR IMPRESSION OF MAZDA AND YOUR DEALERSHIP.**

2. Once you have identified the correct model, click the link below for the procedure that matches the model of vehicle being repaired and complete all repair steps.
  - a. [PHEV model only](#)
  - b. [MHEV model only](#)



**If you need assistance with this repair procedure or for a rejected claim, before contacting any Mazda Support Teams review the FAQ's and Dealer Emails for this campaign in MGSS under recall 7024J and provide all module names, and date of their updates to the Mazda Team member.**