



TECHNICAL SERVICES BULLETIN

TSB number: 824CQ35329
 FA number: FA-US-2025-0002
 Bulletin Title: VF8_Drivers Front Seat Centre Airbag Replacement
 Released by: VF - Aftersales Operation
 Date of issue: 10 Feb 2025
 Applies to: VF Aftersales, Dealers and Showrooms

CHANGE HISTORY

Version	Status	Effective Date	Handled by	Approved by	Comments
1.0	Release	10 Feb 2025	Aftersales Operation	Global Aftersales Service DCEO	Initial EN Release
2.0	Release	17 Feb 2025	Aftersales Operation	Global Aftersales Service DCEO	<ul style="list-style-type: none"> - Updated sections 1.0 and 2.0 - Added step in section 5.0 for Airbag serial numbers

1.0. Overview

Market	US
Field Action Type	Recall
Implementation	VinFast will send customer communications (C-App/SMS/email/telephone call) relating to this field action. Dealerships and Showrooms shall apply this update to applicable vehicles, when entering workshop during customer communication, regular service and/or an unrelated repair.

2.0. Programs and model years impacted

The following programs and model years are impacted by this bulletin:

Market	Model	Manufacturing Year		VIN list
		From	To	
US	VF8	2023	2025	4888 Refer to attachment

3.0. Issue description

VinFast agreed with NHTSA to voluntarily recall affected 2023, 2024 and 2025 MY VinFast VF 8 vehicles to replace the Drivers front seat centre airbag with a redesigned Drivers front seat centre airbag. The redesigned Drivers front seat centre airbag has a different cushion shape, folding dimension and deployment angle that results in a different inflation path.

4.0. Solution summary

Replace the Drivers front seat centre airbag with a redesigned airbag.

5.0. Repair instructions

1. Replace the drivers front seat inboard centre airbag (**Item 2** – Figure 1), refer to the Service Instruction procedure [Front Seat Back Airbag \(Inboard or Outboard\) Removal and Installation/Replacement – 1003789](#).

NOTE:

- Please collect serial numbers of old and new parts for warranty claim.
- Replace with new nuts STD20000075 (x2).




Figure 1

2. Finish.

6.0. Parts information

Service parts applicable to this bulletin.

No	Part number	Part name	Quantity/Vehicle	Note
1	CENTRE AIRBAG	BIN80038012AA	1	
2	HEX NUT WITH FLANGE M6X1.0	STD20000075	2	

7.0. Warranty claim information

The following warranty claim information applies to this bulletin:

Labour code	Description	Labour time (h)	Note
99300116	VF8 US_Front Seat Centre Airbag Replacement	0.75	

Table of contents

CHANGE HISTORY	1
1.0. Overview	1
2.0. Programs and model years impacted	1
3.0. Issue description	1
4.0. Solution summary	2
5.0. Repair instructions	2
6.0. Parts information	2
7.0. Warranty claim information	2