

Parts Bulletin

TITLE:

Recall RP1044: Polestar 2 Far Side Airbag

GROUP:
88

NO:
RP1044

CAR MARKET:
United States

REVISIONS:

ISSUE DATE:
2024-12-18

STATUS DATE:
2024-12-18


Page 1 of 1

Polestar Automotive USA on behalf of Polestar Performance AB, has decided to launch Recall RP1044 on certain model year 2024 Polestar 2 vehicles.

Polestar investigations has determined that the supplier's assembly station had incorrect software control parameters that caused the clamps on the driver side inner Far Side Airbag (FSAB) to not be crimped properly.

As a result, in the event of a crash, the driver side inner FSAB may not deploy correctly, increasing the risk of injury.

DRIVER SEAT



To remedy the concerned vehicles, Polestar will replace the inner FSAB in the driver front seat.

A total of 7 U.S. vehicles are affected by this recall.

Part Number	Qty	Failing Part	Description
32403043	1	F	Air bag module
95722	4		Clamp