



August, 2025

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2022 Escape has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **24S16 - 2022-23 Bronco Sport 1.5L Dragon Fuel Injector Leak**
and Description:

What is the issue? On your vehicle, it may be possible that a fuel injector may crack and leak fuel, which may result in fuel accumulating on the top of the engine.

Liquid fuel and/or fuel vapor that accumulates near a hot surface, such as hot engine or exhaust components may ignite resulting in an under-hood fire, increasing the risk of injury.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Augusto de, 2025

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2022 Escape las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **24S16 - Fuga del inyector de combustible en vehículos Bronco Sport 1.5L Dragon 2022-23**

¿Cuál es el problema? En su vehículo, puede que un inyector de combustible se agriete y filtre combustible, lo cual podría ocasionar una acumulación de combustible en la parte superior del motor.

El combustible líquido o el vapor de combustible que se acumula cerca de una superficie caliente, como un motor o componentes de escape calientes, podría encenderse, lo cual generaría un incendio bajo el cofre y aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0837441 A / 000000000000515 / 515



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

