



November, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2021 Bronco Sport has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **24S24 - Loss of Motor Power**

What is the issue? On your vehicle, the Body Control Module (BCM) and Powertrain Control Module (PCM) calibrations may be unable to detect a sudden change in the 12-volt battery state of charge during a drive cycle.

If the BCM and PCM calibrations are unable to detect a sudden battery degradation during a drive, the vehicle may be unable to restart or may experience a stall while coming to a stop at low speed. The vehicle may also lose electrical accessories such as hazard lights or cause a loss of drive power increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Noviembre de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2021 Bronco Sport las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **24S24 - Pérdida de potencia del motor**

¿Cuál es el problema? En su vehículo, es posible que las calibraciones del módulo de control de la carrocería (BCM) y del módulo de control del tren motriz (PCM) no puedan detectar un cambio repentino en el estado de carga de la batería de 12 voltios durante un ciclo de conducción.

Si las calibraciones del BCM y del PCM no pueden detectar una degradación repentina de la batería durante un viaje, es posible que el vehículo no pueda reiniciarse o que se cale al detenerse a baja velocidad. El vehículo también puede perder accesorios eléctricos, como luces de emergencia, o provocar una pérdida de potencia de conducción, lo que aumenta el riesgo de accidente.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0000523 A / 000000000000712 / 31



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

