



September, 2024

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2024 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **24S32 - 2024 F150 Lower I-Shaft Steering Gear Joint Fastener Incorrect**
and Description:

What is the issue? On your vehicle, it may be possible an incorrect fastener was used to secure the steering column lower shaft to the steering gear.

An incorrect fastener may loosen over time and could disengage. If the fastener disengages, separation of steering system adjoining components may occur, resulting in loss of steering control, which can increase the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**.

If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Septiembre de, 2024

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2024 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **24S32 - Sujetador de la junta del engranaje de la dirección del eje I inferior incorrecto en vehículos F150**

¿Cuál es el problema? En su vehículo, es posible que se haya utilizado un sujetador incorrecto para asegurar el eje inferior de la columna de dirección al mecanismo de dirección.

Un sujetador incorrecto puede aflojarse con el tiempo y soltarse. Si el sujetador se suelta, puede ocurrir la separación de los componentes adyacentes del sistema de la dirección, lo que se traduce en una pérdida de control de la dirección, lo que puede aumentar el riesgo de accidente.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**.

Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


0654939 A / 000000000000526 / 526



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▼ REMOVE THESE SIDE EDGES FIRST
▼ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼



▼ REMOVE THESE SIDE EDGES FIRST
▼ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼