



February, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2024 Explorer has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **24S61 - Insufficient Clearance Between Battery Harness & BISG**
and Description:

What is the issue? In the affected vehicles, the unfused 12 volt battery cable is not secured properly and may contact the starter generator.

If the battery cable contacts the starter generator during vehicle operation, it may cause damage to the battery cable insulation, creating the potential for a short circuit and increasing the risk of a fire.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2024 Explorer las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **24S61 - Espacio libre insuficiente entre el arnés de la batería y el BISG**

¿Cuál es el problema? En los vehículos afectados, el cable de la batería de 12 voltios sin fusible no está asegurado correctamente y puede entrar en contacto con el generador de arranque.

Si el cable de la batería entra en contacto con el generador de arranque durante el funcionamiento del vehículo, puede dañar el aislamiento del cable de la batería, lo cual crea un potencial de cortocircuito y aumenta el riesgo de incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0837443 A / 000000000000851 / 22



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

