



***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 24E-078
Cummins Campaign #C7083
2nd Notice

January 15, 2026



Engines eligible for Cummins Campaign #C7083:

Engine Serial Number	Vehicle Model	Vehicle Identification Number
80667078	PT126SLP	3AKJHHFG1SSVR [REDACTED]
80672154	PT126DC	3AKBHKFG2SDVH [REDACTED]



***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 24E-078
Cummins Campaign #C7083
2nd Notice

January 15, 2026

Dear Cummins Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in certain Cummins X15 engines that were manufactured between June 10, 2024 and August 30, 2024 and certain re-manufactured X15 engines built between August 13, 2024 and August 14, 2024.

This notice applies to your Cummins X15 engine(s) listed in the table on the enclosed engine list.

WHY IS A RECALL BEING CONDUCTED?

The fuel pump barrels installed on some of the engines in the subject population may have been built using low fatigue strength parts, making them susceptible to fracture. If a fuel pump barrel fractures, an external fuel leak and sudden loss of fuel pressure may occur, potentially causing the engine to stall without the ability to restart. An engine stall without the ability to restart may increase the risk of a crash.

WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins has released field Safety Campaign C7083 'X15 Fuel Pump Head Replacement Safety Campaign' to correct this condition by replacing the suspect barrels (2 barrels per fuel pump) with new verified parts. Repair parts are currently available at Cummins Distributors and authorized Warranty Dealers. The repair will be completed free of charge and most applications will require approximately 2 hours to complete.

WHAT SHOULD YOU DO?

Contact the nearest Cummins Distributor or authorized Warranty Dealer to arrange to have this campaign performed on your engine. The distributor or dealer will work with you to schedule the best date to complete this repair.

In the meantime, until the campaign is completed, operators are advised that reduced engine performance, a warning lamp, or the visual observation or smell of diesel fuel around the vehicle may be symptomatic of a fuel pump barrel fracture. If a fuel pump barrel fracture is suspected, Cummins recommends stopping the engine when it is safe to do so and seeking immediate repair.

Federal law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. Also, it is a violation of Federal law for a dealer to deliver a new vehicle or equipment covered by this recall notice under a sale or lease until the defect has been remedied.

If you previously paid to have this recall performed on your vehicle, you may be eligible for reimbursement. Please contact your local Cummins Distributor or authorized warranty dealer. To

Cummins Inc.
Box 3005
Columbus, IN 47202-3005 USA
Mail Code: 40911
Phone: 1 800 CUMMINS
care.cummins.com



***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 24E-078
Cummins Campaign #C7083
2nd Notice

find a service provider near you, please use the Service Locator tool found at the Cummins sponsored website <https://quickserve.cummins.com>.

WHO SHOULD YOU CONTACT IF YOU HAVE FURTHER QUESTIONS OR CONCERNS?

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800-CUMMINS (1-800-286-6467) or visit our website at <https://care.cummins.com>.

If you have a complaint relative to this recall, you may report it to the following:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

In order to serve you better it is important to register your product. If you have not already registered your Cummins product, or your details need to be updated, use one of the following options to register your product. Using your phone or tablet, scan the QR Code below and complete the registration online. Or, using your laptop, you can register your product at <https://prodreg.cummins.com>.

If you are no longer the owner of the engine or vehicle listed in the table, please forward this notice to the new owner or provide the new owner's contact information via email to Cummins at cummins.campaign.administration@cummins.com so that we can update the contact information and notify them of this recall.

Finally, if the engine has been scrapped, or otherwise taken out of service, and replaced with another Cummins product, please contact your local Cummins Distributor or authorized warranty dealer for assistance in handling the necessary updates for your Cummins product.

Cummins is taking this action in the interest of safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,

Campaign Administrator
Cummins Inc.

Scan the QR code and complete the registration of your Cummins product online.



Cummins Inc.
Box 3005
Columbus, IN 47202-3005 USA
Mail Code: 40911
Phone: 1 800 CUMMINS
care.cummins.com