



February, 2026

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2024 Ranger has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number** 24S71 - Fuel Line to Bracket Insufficient Clearance  
**and Description:**

**What is the issue?** On your vehicle, a fuel vapor line bracket may have been installed in error, resulting in inadequate clearance between the bracket and the fuel vapor line. The fuel vapor line may contact the bracket and, over time, become damaged.

If the fuel vapor line is damaged, this can result in fuel vapor leakage. A fuel vapor leak in the presence of an ignition source increases the risk of fire.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Febrero de, 2026

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2024 Ranger las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 24S71 - Espacio libre insuficiente entre la línea de combustible y el soporte

**¿Cuál es el problema?** Es posible que en su vehículo se haya instalado por error un soporte de la tubería de vapor de combustible, lo que da como resultado un espacio inadecuado entre el soporte y la tubería de vapor de combustible. La tubería de vapor de combustible puede entrar en contacto con el soporte y, con el tiempo, dañarse.

Si la tubería de vapor de combustible está dañada, esto puede provocar una fuga de vapor de combustible. Una fuga de vapor de combustible en presencia de una fuente de encendido aumenta el riesgo de incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0827637 A / 000000000000872 / 33



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

