



PETERBILT MOTORS COMPANY

A PACCAR COMPANY

1700 WOODBROOK STREET
DENTON, TEXAS 76205-7864
940-591-4000


P.O. BOX 90208
DENTON TEXAS 76202-5208

IMPORTANT SAFETY RECALL INFORMATION

Issued in Accordance
With Federal Law



IMPORTANT SAFETY RECALL



*****SNGLP



000001
T1 P1

24PBJ

Important Safety Recall: 24PBJ

IMPORTANT SAFETY RECALL

IMPORTANT SAFETY RECALL

Interim Notification

December 24, 2024.

This notice applies to your vehicle. Your VIN(s) can be found on the bottom or back of this page.

Subject: Safety Recall: 24PBJ - Meritor Front Steer Drive Axle Hub Lubrication
NHTSA: 24V903
EXPIRATION DATE: NONE

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2024-2025, 536, 537, and 548 vehicles manufactured from 09/11/2023 through 08/28/2024 with Meritor 10-16K and 18-23K Front Steer Drive Axles. Meritor 10-16K and 18-23K Front Steer Drive Axles may have insufficient wheel bearing grease. Insufficient lubrication in the wheel bearing may cause the wheel hub to overheat and become damaged, which may increase the risk of fire. The driver may hear noise, excessive steering play, and/or smoke from the front wheel, which may increase the risk of a crash.

What is the problem?	Meritor 10-16K and 18-23K Front Steer Drive Axles may have insufficient wheel bearing grease, which may cause the wheel hub to overheat and could result in damaging wheel bearings, and increase the risk of fire.
What will your dealer do?	When parts are available, your dealer will inspect the wheel bearing, if it is found defective, the dealer will replace it with new wheel bearing parts.
What should you do?	There is no action required on your part at this time.

Peterbilt Motors Company has initiated this recall to remedy the issue with no charge to you. **Currently, parts are unavailable to correct this condition.** However, Peterbilt is required to notify customers of the existence of the identified safety defect. **You will be notified by mail when the parts become available.**

If you require further information about this recall or experience any difficulty in making arrangements for this repair, please contact the Peterbilt Customer Experience Department at PB.Tech.Pubs.Dept@paccar.com.

If you conclude that Peterbilt has not enabled you to remedy this defect in a reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner. Please send all known ownership and address changes to PBDiv.Warranty.Docs@paccar.com.

We apologize for any inconvenience this preventive procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise. We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,



Michelle Ponsonby
Director of Customer Experience
Peterbilt Motors Company

Our records indicate that these vehicles are affected by 24PBJ and are owned by [REDACTED]

[REDACTED]