

EQUIPMENT RECALL N964 – DEFENDER RAISED AIR INTAKE

EQUIPMENT SAFETY RECALL N964 – RAISED AIR INTAKE	
AFFECTED MODELS / PART NUMBER	20-25MY Defender Part Number: VPLEP0543
VOLUME AFFECTED	Potential number of parts in USA 485 and 26 in Canada.
REPAIR	A concern has been identified with the accessory raised air intake where there is a dimensional tolerance mismatch between the lower fixing on the raised air intake and the body A-pillar to which it mounts. This tolerance mismatch can result in inadequate attachment force between the raised air intake and the vehicle.
REPAIR TIME	Est. 0.6 hrs + DIDO
CAMPAIGN LAUNCH	A retailer N964 Recall Admin bulletin was posted on TOPIx on December 19th, 2025. A repair bulletin will be published when all required procedures and parts are available.
NOTES	Accessory sales are now blocked in US/CAN. Retailers must stop installing this accessory and stop selling vehicles with the accessory already installed. ACTION: Retailers are requested to search their records and identify and report all vehicles where they have completed the raised intake accessory installation using part VPLEP0543. Follow bulletin instructions on reporting of affected VIN. Retailers have also been requested to return unused parts stock to their PDC.