

Toyota Motor North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Stop: W4-2D
6565 Headquarters Drive
Plano, TX 75024

July 25, 2024

AMENDMENT TO DEFECT INFORMATION REPORT (24V-381)

This amends Toyota's Part 573 Report of May 30, 2024 concerning the engine debris issue on certain Toyota and Lexus vehicles.

The Description of Corrective Repair Action is revised as noted below:

Description of Corrective Repair Action:

All known owners of the subject vehicles will be notified to return their vehicles to a Toyota or Lexus dealer. The dealer will replace the engine assembly with a new one, free of charge.