

STOP SALE NOTICE



SERVICE CAMPAIGN: 001114

FR ID: 22-1789

May 31, 2024

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

“It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law.”

CANADA: Pursuant to the Canadian Motor Vehicle Safety Act, section 5

Companies who sell new non-complying vehicles may be in violation of the Motor Vehicle Safety Act. Substantial penalties apply to violations of this law. This notice is being sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Pursuant to Federal Motor Vehicle Safety Act; 49 CFR Part 573.11; this notice shall serve as a formal

SAFETY RECALL - STOP SALE NOTIFICATION.

2024 RAINIER RNT18DBR, SALEM SMT189RSK, SMT191SS, STEALTH EVO SJT189RS, SJT192SS, VIBE VBT16RB, VBT17RS, VBT18DB, AND WILDWOOD WDT189RSK

Forest River has decided that a safety defect exists in certain 2024 Rainier RNT18DBR, Salem SMT189RSK, SMT191SS, Stealth Evo SJT189RS, SJT192SS, Vibe VBT16RB, VBT17RS, VBT18DB, and Wildwood WDT189RSK Travel Trailers. Forest River is recalling the defective model(s) to ensure the safety of our future retail consumers and your dealership. Forest River is issuing a Stop Sale Notice effective immediately.

Please access your Home Page on Dealer Connect to verify if your Dealership has units in stock that are subject to this recall. Enter the Service Campaign number referenced above in the “Campaign Search” field and click on the “Campaign ID Number”. Next, select “MY VINS”. Not all Dealers have units in stock that are affected by this recall.

DEFECT/NONCOMPLIANCE:

Under full jounce of the axle, the tire may contact the structure above the tire, which may lead to tire failure.

EVALUATION OF RISK:

If the tire contacts the structure, the tire may fail leading to loss of vehicle control and causing a crash.

SERVICE PROCEDURE:

The remedy is under development. A second notice will be sent when the remedy is available.

HELPFUL CONTACT INFORMATION:

CONTACT	PHONE
CUSTOMER SERVICE	(503) 831-5410