

URGENT SAFETY RECALL NOTICE

Your 2022 RAM 1500 PROMASTER C/V HR 136 WB is under recall for 2nd Row Seating Regulatory Compliance.

To schedule your recall repair contact your dealership or the FCA US Recall Team at **1-800-853-1403**.

Recall notice issued to:

[REDACTED]

Vehicle information:

VIN

[REDACTED]

2022 RAM 1500 PROMASTER C/V HR 136 WB

Recall information: 53B/NHTSA 24V-416

Visit recalls.mopar.com for more information or call the FCA US Recall Team at **1-800-853-1403**

Details of the Recall

Your vehicle may have been built with an inaccurate tire placard and second-row seat configuration that did not include a side door beam. Vehicles missing a side door beam or with an inaccurate tire placard may not provide adequate protection increasing the risk of injury to the occupants of the vehicle during certain crashes.

FCA US LLC will repair your vehicle free of charge (parts and labor). To do this, your dealer will install a door beam and update the tire placard label. The estimated repair time is one hour. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience. Ask your dealer for alternate transportation options while your vehicle is in service.

How do I schedule my **FREE** repair?

- ◆ Simply contact your Chrysler, Jeep®, Dodge or RAM dealer right away to schedule a service appointment.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations

FCA US LLC Team

[1-800-853-1403](tel:1-800-853-1403)

recalls.mopar.com