

**24V-611**  
**In-Car / In-App Communication – Safety Recall Reminder**  
**26 Dec 2024**

**Title**

BMW Safety Recall 24V-611: Side Beam

**Text**

On the vehicle's left-hand side, toward the rear of the vehicle, a side beam may not have been produced by the supplier to specifications. In a crash, this area could be damaged, which could increase the risk of injury to rear seat occupants. It could also cause damage to the high voltage battery housing, which could increase the risk of a fire.

Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: [bmwusa.com/dealer](https://www.bmwusa.com/dealer).

Advise all drivers of this important information.

For the latest updates to this recall, please visit [bmwusa.com/recall](https://www.bmwusa.com/recall).

**Short Text**

Important Safety Recall 24V-611: Side Beam. Contact an authorized BMW center immediately to get your vehicle repaired for FREE.

**Pop-Up Text**

Important Safety Recall: Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: [bmwusa.com/dealer](https://www.bmwusa.com/dealer).