

# STOP SALE NOTICE



SERVICE CAMPAIGN: 001142

FR ID: 69-1833

August 22, 2024

## **Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B**

“It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law.”

## **CANADA: Pursuant to the Canadian Motor Vehicle Safety Act, section 5**

*Companies who sell new non-complying vehicles may be in violation of the Motor Vehicle Safety Act. Substantial penalties apply to violations of this law. This notice is being sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.*

Pursuant to Federal Motor Vehicle Safety Act; 49 CFR Part 573.11; this notice shall serve as a formal

## **SAFETY RECALL - STOP SALE NOTIFICATION.**

**2024-2025 SALEM SBF325RL AND WILDWOOD WBF325RL FIFTH WHEELS**

**The designated date range for production is 10/18/2023 – 08/14/2024**

Please access your Home Page on Dealer Connect to verify if your Dealership has units in stock that are subject to this recall. Enter the Service Campaign number referenced above in the “Campaign Search” field and click on the “Campaign ID Number.” Next, select “MY VINS.” **Not all Dealers have units in stock that are affected by this recall.**

Forest River has decided that certain 2024-2025 Salem SBF325RL and Wildwood WBF325RL Fifth Wheel Recreational Vehicles have a safety defect. To ensure the safety of our future retail consumers and your dealership, Forest River is recalling the defective model (s) and issuing a Stop Sale Notice effective immediately.

### **WHAT IS THE DEFECT?**

The tire(s) may contact chassis components.

### **EVALUATION OF RISK:**

If the tire contacts the chassis components, it may fail. This condition may lead to loss of vehicle control, which may lead to a crash.

### **SERVICE PROCEDURE:**

The remedy is being developed. Once it is available, a second notice will be sent.

### **HELPFUL CONTACT INFORMATION:**

| CONTACT          | PHONE          |
|------------------|----------------|
| CUSTOMER SERVICE | (574) 534-3167 |