

SAFETY RECALL H516/N927 - BOSCH NEAR FIELD SENSING MODULE (NFSM)

SAFETY RECALL H516/N927 - BOSCH NEAR FIELD SENSING MODULE (NFSM)

AFFECTED MODELS	25MY F-PACE 25MY Range Rover, Range Rover Sport, Range Rover Evoque, and Discovery Sport
VOLUME AFFECTED	JAG US 5 CAN 10 LR US 180 CAN 13
REPAIR	A concern has been identified on a limited number of vehicles, where thermal paste has not been applied correctly on the Near Field Sensing Module (NFSM), without thermal paste applied, the module can overheat, and this may result in camera images not being displayed.
REPAIR TIME	1.7 hrs + DIDO
CAMPAIGN LAUNCH	Quarantine Notification published on August 30th, 2024 Recall repair was launched on September 25th, 2024
NOTES	Please refer to the warranty portal for affected vehicles and in BBSS to identify affected vehicles in inventory which must be repaired before sale and delivery. All sold vehicles should have the recall completed at the next earliest opportunity 7 affected vehicles are in retailer stock.