



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

March 7, 2025

Mr. Charles Smart
Head of Claims Management Dept
Triumph Motorcycles America, Ltd.
Normandy Way
Hinckley LE10 3BZ

NEF-107DM
25V-141

Subject: Rear Turn Signals Too Close to Tail Lights

Dear Mr. Smart:

This letter serves to acknowledge Triumph Motorcycles America, Ltd.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TRIUMPH/SPEED TWIN 1200/2025
TRIUMPH/SPEED TWIN 1200 RS/2025
TRIUMPH/SPEED TWIN 900/2025

Mfr's Report Date: March 4, 2025

NHTSA Campaign Number: 25V-141

Components:

EXTERIOR LIGHTING:TURN SIGNAL

Potential Number of Units Affected: 1,157

Problem Description:

Triumph Motorcycles America, Ltd. (Triumph) is recalling certain 2025 Speed Twin 1200, Speed Twin 1200 RS, and Speed Twin 900 motorcycles. The red rear turn signals were installed too close to the rear tail light. As such, these motorcycles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, reflective devices, and associated Equipment."

Consequence:

Rear turn signals that are too close to the tail lights can cause difficulty seeing the motorcycle's intentions, increasing the risk of a crash.

Remedy:

Dealers will replace the red rear turn signals with amber colored turn signals, free of charge. Owner notification letters are expected to be mailed March 14, 2025. Owners may contact Triumph customer service at 1-678-854-2010. Triumph's number for this recall is SRAN 630.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 888-327-4236 (TTY 888-275-9171) or go to [nhtsa.gov](https://www.nhtsa.gov).



We have received Triumph's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:


Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Triumph Motorcycles America, Ltd.'s contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement