



U.S. Department of Transportation

**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 11, 2025

25V505

Robert Alsip
Suzuki Motor USA, LLC
3251 E. Imperial Highway
Brea, CA 92821

Subject: Upper Headlight Beam is Too Bright/FMVSS 108

Dear Robert Alsip:

This letter serves to acknowledge Suzuki Motor USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SUZUKI/DL1050/2020-2025
SUZUKI/GSX-S1000S/2020, 2024

Mfr's Report Date: August 07, 2025

NHTSA Campaign Number: 25V505

Components:

EXTERIOR LIGHTING:HEADLIGHTS

Potential Number of Units Affected: 1,543

Problem Description:

Suzuki Motor USA, LLC (Suzuki) is recalling certain 2020-2025 DL 1050 and 2020, 2024 GSX-1000S motorcycles. The upper headlight beam may be too bright and exceed the maximum light output, which may adversely affect the vision of the driver. As such, these vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence:

Headlights that are excessively bright can reduce visibility for oncoming drivers, increasing the risk of a crash.

Remedy:

Suzuki dealers will replace the headlight assembly, free of charge. Interim owner notification letters are scheduled to be mailed on August 29, 2025. Second letters will be sent once the final remedy is available. Owners may contact Suzuki customer service at 1-800-934-0934. Suzuki's number for this recall is 3A06/3A07.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

We have received your proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Suzuki Motor USA, LLC's contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement